

Analysis of Needs Assessment Surveys for Potential Capital Improvement Project


The Lake George Central School District asked staff members to complete a Needs Assessment survey of the building in which they are located. The survey was emailed to all staff members. The survey began 6/11/18 and ended 7/10/18.

LGES Respondents: 29

Jr.-Sr. HS Respondents: 36

The district asked community members to complete a Needs Assessment survey of both school buildings. The survey was emailed two times to 1,188 individuals and posted on the district website. The survey began 6/13/2018 and ended 7/10/18.

Community Respondents: 111



The response set from both Needs Assessment Surveys was 176. This represents approximately 15% of the 1,188 individuals emailed. The respondent pool was less than 4% of the eligible voters (5,500) in the Lake George CSD.

1. LGES Staff Perceptions

Quality of classrooms in terms of ability to support educational program needs:

Safety and security of classrooms is most in need of improvement

2.46 average out of 5, with 5 being the least in need of improvement

10/17 comments related to security reinforce this perception

Quality of exterior of building in terms of ability to support educational program needs:

Safety and security of the building is most in need of improvement

2.97 average out of 5, with 5 being the least in need of improvement

Quality of other areas of the building in terms of their ability to support education program needs:

Storage space is most in need of improvement

3.17 out of 5, with 5 being the least in need of improvement

2. Jr.-Sr. HS Staff Perceptions

Quality of classrooms in terms of ability to support educational program needs:

Safety and security of classrooms is most in need of improvement

3.58 average out of 5, with 5 being the least in need of improvement

8/19 comments related to window safety reinforce this perception

Quality of exterior of building in terms of ability to support educational program needs:

Faculty/staff parking is most in need of improvement

1.94 average out of 5, with 5 being the least in need of improvement

Quality of other areas of the building in terms of their ability to support education program needs:

Storage space is most in need of improvement (2.78 out of 5), with

Restrooms coming in close second as most in need of improvement

2.86 out of 5, with 5 being the least in need of improvement

4/19 comments about restrooms

4/19 comments about A/C

3. Community Perceptions

Needs of LGES interior spaces:

Security is most in need of improvement

2.36 average out of 5, with 5 being the least in need of improvement

6/44 comments about safety

Quality of exterior of LGES:

Athletic fields are most in need of improvement

3.16 average out of 5, with 5 being the least in need of improvement

8/44 comments about athletics

Other areas of LGES:

Overall technology is most in need of improvement

2.89 out of 5, with 5 being the least in need of improvement

Needs of Jr.-Sr. HS interior spaces:

Security is most in need of improvement

2.17 average out of 5, with 5 being the least in need of improvement

6/44 comments about safety

Quality of exterior of Jr.-Sr. HS:

Community parking is most in need of improvement

2.37 average out of 5, with 5 being the least in need of improvement

3/44 comments about parking

Other areas of Jr.-Sr. HS:

Student support services areas are most in need of improvement

2.9 out of 5, with 5 being the least in need of improvement

Community responses were different from staff responses in the following areas:

	Community Response	LGES Staff Response
Restrooms	2.91	3.41
Handicap accessibility	3.17	4.24
Faculty/Staff parking	4.06	4.03
Community parking	3.33	4.1
Drop-off and pick-up areas	3.48	3.9
Bus loops	3.72	4.14
Athletic fields	3.16	4.14
Cafeteria Space	3.41	4.28
Library Media Center	3.53	4.66
Office Areas	3.7	4.34
Art rooms	3.36	4.14
Music Rooms	3.33	4.14
Performance Spaces	3.15	4.1
Gymnasium	3.1	4.46
Student Support Services	3.06	3.93
Storage Space	3.46	3.17
Overall Technology	2.89	4.61

	Community Response	HS Staff Response
Restrooms	2.93	2.86
Handicap accessibility	2.87	3.03
Faculty/Staff parking	2.55	1.94
Community parking	2.37	2.06
Drop-off and pick-up areas	2.6	2.89
Bus loops	3.28	3.47
Athletic fields	2.93	3.83
Cafeteria Space	3.21	4.11
Library Media Center	3.52	4.63
Office Areas	3.84	4.25
Art rooms	3.26	4.17
Music Rooms	3.4	4.17
Performance Spaces	3.31	4.34
Gymnasium	3.58	4.42
Student Support Services	2.9	4.03
Storage Space	3.33	2.78
Overall Technology	2.91	4.46

	LGES Staff Response	Community Response	HS Staff Response	Community Response
"A"	17%	18%	19%	8%
"B"	45%	48%	44%	40%
"C"	38%	28%	31%	37%
"D"		6%	6%	14%
"F"				2%

[Back](#)

Needs Assessment Survey for Staff Results Overview

★ = Your Response

Respondents: 29 displayed, 65 total

Status: Open

Launched Date: N/A

Closed Date: 07/10/2018

Display: 

Active Report Filters:

Filter Type: Question;
QuestionID: 124 AnswerID: 145

Manage Filters: 1 filter

Share Results: Enabled

[More](#)

1. In which building are you located?

	Response Total	Response Percent
Lake George Elementary School	29	100%
Lake George Jr.-Sr. High School	0	0%
Bus Garage	0	0%
Total Respondents	29	

2. What is your department/position?

	Response Total	Response Percent
Faculty	24	83%
Support Staff - Aide	3	10%
Support Staff - Clerical	2	7%
Buildings and Grounds	0	0%
Technology	0	0%
Transportation	0	0%
Food Services	0	0%
Total Respondents	29	

3. Please rate your perception of the quality of the classrooms in terms of their ability to support our educational program needs (with one being the least and five being the best).

	1	2	3	4	5	Response Total	Response Average
Adequate number	0% (0)	6.9% (2)	3.45% (1)	27.59% (8)	62.07% (18)	29	4.45
Appropriate size	0% (0)	10.34% (3)	13.79% (4)	31.03% (9)	44.83% (13)	29	4.1
Appropriate location	0% (0)	3.57% (1)	14.29% (4)	32.14% (9)	50% (14)	28	4.29
Adequate furnishings	0% (0)	3.45% (1)	17.24% (5)	27.59% (8)	51.72% (15)	29	4.28
Adequate lighting	3.45% (1)	3.45% (1)	10.34% (3)	27.59% (8)	55.17% (16)	29	4.28
Adequate technology	0% (0)	0% (0)	3.7% (1)	14.81% (4)	81.48% (22)	27	4.78
Safety and security	14.29% (4)	39.29% (11)	32.14% (9)	14.29% (4)	0% (0)	28	2.46
Total Respondents						29	

4. Please rate your perception of the quality of the exteriors of the building in terms of its ability to support our educational program needs (with one being the least and five being the best).

	1	2	3	4	5	Response Total	Response Average
Faculty/staff parking	3.45% (1)	6.9% (2)	20.69% (6)	20.69% (6)	48.28% (14)	29	4.03
Community parking	0% (0)	6.9% (2)	24.14% (7)	20.69% (6)	48.28% (14)	29	4.1
Safety/security of the building	10.34% (3)	20.69% (6)	41.38% (12)	17.24% (5)	10.34% (3)	29	2.97
Drop-off and pick-up areas	0% (0)	3.45% (1)	37.93% (11)	24.14% (7)	34.48% (10)	29	3.9
Bus loops	0% (0)	0% (0)	20.69% (6)	44.83% (13)	34.48% (10)	29	4.14
Adequate and functioning windows and doors	10.34% (3)	24.14% (7)	24.14% (7)	20.69% (6)	20.69% (6)	29	3.17
Handicap accessibility	0% (0)	0% (0)	20.69% (6)	34.48% (10)	44.83% (13)	29	4.24

Survey Results

Playground space and equipment	3.45% (1)	0% (0)	10.34% (3)	34.48% (10)	51.72% (15)	29	4.31
Athletic fields	10.34% (3)	3.45% (1)	3.45% (1)	27.59% (8)	55.17% (16)	29	4.14
						Total Respondents	29

5. Please rate your perception of the quality of the other areas of the building in terms of their ability to support our educational program needs (with one being the least and five being the best).

	1	2	3	4	5	Response Total	Response Average
Cafeteria Space	0% (0)	0% (0)	20.69% (6)	31.03% (9)	48.28% (14)	29	4.28
Restrooms	3.45% (1)	10.34% (3)	51.72% (15)	10.34% (3)	24.14% (7)	29	3.41
Library Media Center	0% (0)	0% (0)	10.34% (3)	13.79% (4)	75.86% (22)	29	4.66
Office Areas	0% (0)	3.45% (1)	10.34% (3)	34.48% (10)	51.72% (15)	29	4.34
Art/Music Rooms	0% (0)	7.14% (2)	17.86% (5)	28.57% (8)	46.43% (13)	28	4.14
Gymnasium	0% (0)	0% (0)	10.71% (3)	32.14% (9)	57.14% (16)	28	4.46
Auditorium	0% (0)	10.34% (3)	17.24% (5)	24.14% (7)	48.28% (14)	29	4.1
Student Support Services	3.57% (1)	0% (0)	32.14% (9)	28.57% (8)	35.71% (10)	28	3.93
Storage Space	17.24% (5)	10.34% (3)	31.03% (9)	20.69% (6)	20.69% (6)	29	3.17
Internal Communication Systems	3.45% (1)	6.9% (2)	37.93% (11)	34.48% (10)	17.24% (5)	29	3.55
Overall Technology	0% (0)	0% (0)	3.57% (1)	32.14% (9)	64.29% (18)	28	4.61
						Total Respondents	29

6. Please give an overall letter grade for the condition of your school building(s).

	Response Total	Response Percent
A	5	17%
B	13	45%
C	11	38%
D	0	0%
F	0	0%
		Total Respondents
		29

7. Comments

	Response Total	Response Percent
view Comments	17	100%
		Total Respondents
		17
		(skipped this question)
		12

Back

Needs Assessment Survey for Staff Results Overview

★ = Your Response

Respondents: 36 displayed, 65 total

Status: Open

Launched Date: N/A

Closed Date: 07/10/2018

Display: 

Active Report Filters:

Filter Type: Question;
QuestionID: 124 AnswerID: 146

Manage Filters: 1 filter

Share Results: Enabled

More

1. In which building are you located?

	Response Total	Response Percent
Lake George Elementary School	0	0%
Lake George Jr.-Sr. High School	36	100%
Bus Garage	0	0%
Total Respondents	36	

2. What is your department/position?

	Response Total	Response Percent
Faculty	28	78%
Support Staff - Aide	2	6%
Support Staff - Clerical	4	11%
Buildings and Grounds	2	6%
Technology	0	0%
Transportation	0	0%
Food Services	0	0%
Total Respondents	36	

3. Please rate your perception of the quality of the classrooms in terms of their ability to support our educational program needs (with one being the least and five being the best).

	1	2	3	4	5	Response Total	Response Average
Adequate number	0% (0)	8.57% (3)	14.29% (5)	34.29% (12)	42.86% (15)	35	4.11
Appropriate size	0% (0)	0% (0)	36.11% (13)	27.78% (10)	36.11% (13)	36	4
Appropriate location	0% (0)	0% (0)	22.86% (8)	42.86% (15)	34.29% (12)	35	4.11
Adequate furnishings	0% (0)	8.33% (3)	19.44% (7)	41.67% (15)	30.56% (11)	36	3.94
Adequate lighting	2.86% (1)	0% (0)	11.43% (4)	48.57% (17)	37.14% (13)	35	4.17
Adequate technology	0% (0)	0% (0)	13.89% (5)	27.78% (10)	58.33% (21)	36	4.44
Safety and security	2.78% (1)	16.67% (6)	25% (9)	30.56% (11)	25% (9)	36	3.58
Total Respondents						36	

4. Please rate your perception of the quality of the exteriors of the building in terms of its ability to support our educational program needs (with one being the least and five being the best).

	1	2	3	4	5	Response Total	Response Average
Faculty/staff parking	38.89% (14)	36.11% (13)	16.67% (6)	8.33% (3)	0% (0)	36	1.94
Community parking	33.33% (12)	38.89% (14)	19.44% (7)	5.56% (2)	2.78% (1)	36	2.06
Safety/security of the building	11.11% (4)	13.89% (5)	30.56% (11)	36.11% (13)	8.33% (3)	36	3.17
Drop-off and pick-up areas	14.29% (5)	17.14% (6)	40% (14)	22.86% (8)	5.71% (2)	35	2.89
Bus loops	5.88% (2)	8.82% (3)	32.35% (11)	38.24% (13)	14.71% (5)	34	3.47
Adequate and functioning windows and doors	28.57% (10)	25.71% (9)	31.43% (11)	14.29% (5)	0% (0)	35	2.31
Handicap accessibility	5.56% (2)	27.78% (10)	33.33% (12)	25% (9)	8.33% (3)	36	3.03

Survey Results

Playground space and equipment	5.88% (2)	8.82% (3)	29.41% (10)	41.18% (14)	14.71% (5)	34	3.5
Athletic fields	0% (0)	8.33% (3)	22.22% (8)	47.22% (17)	22.22% (8)	36	3.83
						Total Respondents	36

5. Please rate your perception of the quality of the other areas of the building in terms of their ability to support our educational program needs (with one being the least and five being the best).

	1	2	3	4	5	Response Total	Response Average
Cafeteria Space	0% (0)	5.56% (2)	16.67% (6)	38.89% (14)	38.89% (14)	36	4.11
Restrooms	22.86% (8)	14.29% (5)	25.71% (9)	28.57% (10)	8.57% (3)	35	2.86
Library Media Center	0% (0)	0% (0)	5.71% (2)	25.71% (9)	68.57% (24)	35	4.63
Office Areas	2.78% (1)	0% (0)	11.11% (4)	41.67% (15)	44.44% (16)	36	4.25
Art/Music Rooms	0% (0)	0% (0)	22.22% (8)	38.89% (14)	38.89% (14)	36	4.17
Gymnasium	0% (0)	0% (0)	5.56% (2)	47.22% (17)	47.22% (17)	36	4.42
Auditorium	0% (0)	0% (0)	14.29% (5)	37.14% (13)	48.57% (17)	35	4.34
Student Support Services	0% (0)	5.56% (2)	16.67% (6)	47.22% (17)	30.56% (11)	36	4.03
Storage Space	19.44% (7)	19.44% (7)	30.56% (11)	25% (9)	5.56% (2)	36	2.78
Internal Communication Systems	2.78% (1)	16.67% (6)	30.56% (11)	33.33% (12)	16.67% (6)	36	3.44
Overall Technology	0% (0)	0% (0)	2.86% (1)	48.57% (17)	48.57% (17)	35	4.46
						Total Respondents	36

6. Please give an overall letter grade for the condition of your school building(s).

	Response Total	Response Percent
A	7	19%
B	16	44%
C	11	31%
D	2	6%
F	0	0%
		Total Respondents
		36

7. Comments

	Response Total	Response Percent
view Comments	19	100%
		Total Respondents
		19
		(skipped this question)
		17

[Back](#)

Needs Assessment Survey for Community Results Overview

★ = Your Response

Respondents: 111 displayed, 111 total

Status: Open

Launched Date: N/A

Closed Date: 07/09/2018

Display: 

Active Report Filters: None Active.

Manage Filters: 0 filters

Share Results: Enabled

More

1. I am a:

	Response Total	Response Percent
Parent of a Lake George Elementary School student	42	38%
Parent of a Lake George Jr.-Sr. High School student	54	49%
Grandparent of children who attend LGCSD	2	2%
District Resident	38	34%
LGCSD Employee	24	22%
LGCSD Retiree	6	5%
LGCSD Alumni	19	17%
LGCSD Student	0	0%
Total Respondents	111	

2. Interior spaces Elementary School (with one being the most in need of improvement and five being the least in need of improvement).

	1	2	3	4	5	Response Total	Response Average
Security Improvements	40.74% (44)	15.74% (17)	22.22% (24)	9.26% (10)	12.04% (13)	108	2.36
Handicap accessibility improvements	15.6% (17)	15.6% (17)	29.36% (32)	15.6% (17)	23.85% (26)	109	3.17
Classroom renovation	11.21% (12)	24.3% (26)	29.91% (32)	17.76% (19)	16.82% (18)	107	3.05
Infrastructure maintenance/replacements	22.02% (24)	24.77% (27)	29.36% (32)	11.93% (13)	11.93% (13)	109	2.67
Restrooms	19.81% (21)	16.04% (17)	32.08% (34)	17.92% (19)	14.15% (15)	106	2.91
Locker rooms	12.5% (13)	10.58% (11)	34.62% (36)	12.5% (13)	29.81% (31)	104	3.37
Total Respondents						111	

3. Interior spaces Jr.-Sr. High School (with one being the most in need of improvement and five being the least in need of improvement).

	1	2	3	4	5	Response Total	Response Average
Security Improvements	44.95% (49)	22.02% (24)	14.68% (16)	7.34% (8)	11.01% (12)	109	2.17
Handicap accessibility improvements	21.3% (23)	18.52% (20)	27.78% (30)	16.67% (18)	15.74% (17)	108	2.87
Classroom renovation	12.5% (13)	25% (26)	38.46% (40)	15.38% (16)	8.65% (9)	104	2.83
Infrastructure maintenance/replacements	30.19% (32)	21.7% (23)	28.3% (30)	11.32% (12)	8.49% (9)	106	2.46
Restrooms	15.53% (16)	23.3% (24)	27.18% (28)	20.39% (21)	13.59% (14)	103	2.93
Locker rooms	13.21% (14)	16.98% (18)	22.64% (24)	19.81% (21)	27.36% (29)	106	3.31
Total Respondents						111	

4. Exterior Qualityfor the Elementary School (with one being the most in need of improvement and five being the least in need of improvement).

	1	2	3	4	5	Response Total	Response Average
Faculty/staff parking	7.62% (8)	4.76% (5)	16.19% (17)	17.14% (18)	54.29% (57)	105	4.06
Community parking	18.18% (20)	10.91% (12)	20.91% (23)	20% (22)	30% (33)	110	3.33

Survey Results

Drop-off and pick-up areas	15.09% (16)	9.43% (10)	22.64% (24)	17.92% (19)	34.91% (37)	106	3.48
Bus loops	10.68% (11)	7.77% (8)	21.36% (22)	19.42% (20)	40.78% (42)	103	3.72
Athletic fields	19.63% (21)	10.28% (11)	26.17% (28)	22.43% (24)	21.5% (23)	107	3.16
Other grounds	14.15% (15)	10.38% (11)	19.81% (21)	27.36% (29)	28.3% (30)	106	3.45
Sidewalks	7.55% (8)	9.43% (10)	25.47% (27)	27.36% (29)	30.19% (32)	106	3.63
Building entrances	13.08% (14)	8.41% (9)	23.36% (25)	27.1% (29)	28.04% (30)	107	3.49
Building exteriors	11.43% (12)	8.57% (9)	28.57% (30)	19.05% (20)	32.38% (34)	105	3.52
						Total Respondents	111

5. Exterior Quality for the Jr.-Sr. High School (with one being the most in need of improvement and five being the least in need of improvement).

	1	2	3	4	5	Response Total	Response Average
Faculty/staff parking	36.45% (39)	18.69% (20)	16.82% (18)	9.35% (10)	18.69% (20)	107	2.55
Community parking	41.44% (46)	21.62% (24)	11.71% (13)	9.01% (10)	16.22% (18)	111	2.37
Drop-off and pick-up areas	29.25% (31)	22.64% (24)	23.58% (25)	7.55% (8)	16.98% (18)	106	2.6
Bus loops	14.42% (15)	12.5% (13)	30.77% (32)	15.38% (16)	26.92% (28)	104	3.28
Athletic fields	22.94% (25)	16.51% (18)	23.85% (26)	18.35% (20)	18.35% (20)	109	2.93
Other grounds	7.55% (8)	16.04% (17)	30.19% (32)	19.81% (21)	26.42% (28)	106	3.42
Sidewalks	6.73% (7)	8.65% (9)	25.96% (27)	22.12% (23)	36.54% (38)	104	3.73
Building entrances	19.81% (21)	21.7% (23)	15.09% (16)	13.21% (14)	30.19% (32)	106	3.12
Building exteriors	10.68% (11)	12.62% (13)	18.45% (19)	20.39% (21)	37.86% (39)	103	3.62
						Total Respondents	111

6. Other Areas for the Elementary School (with one being the most in need of improvement and five being the least in need of improvement).

	1	2	3	4	5	Response Total	Response Average
Cafeteria Space	10.28% (11)	15.89% (17)	24.3% (26)	21.5% (23)	28.04% (30)	107	3.41
Library Media Center	8.57% (9)	17.14% (18)	23.81% (25)	13.33% (14)	37.14% (39)	105	3.53
Office Areas	4.81% (5)	10.58% (11)	29.81% (31)	19.23% (20)	35.58% (37)	104	3.7
Art Rooms	6.73% (7)	18.27% (19)	32.69% (34)	17.31% (18)	25% (26)	104	3.36
Music Rooms	5.77% (6)	20.19% (21)	34.62% (36)	14.42% (15)	25% (26)	104	3.33
Performance spaces	17.27% (19)	15.45% (17)	26.36% (29)	16.36% (18)	24.55% (27)	110	3.15
Gymnasium	18.69% (20)	15.89% (17)	27.1% (29)	13.08% (14)	25.23% (27)	107	3.1
Student Support Services	15.89% (17)	19.63% (21)	29.91% (32)	12.15% (13)	22.43% (24)	107	3.06
Storage Space	8.74% (9)	13.59% (14)	31.07% (32)	16.5% (17)	30.1% (31)	103	3.46
Overall Technology	22.94% (25)	18.35% (20)	27.52% (30)	9.17% (10)	22.02% (24)	109	2.89
						Total Respondents	111

7. Other Areas for the Jr.-Sr. High School (with one being the most in need of improvement and five being the least in need of improvement).

	1	2	3	4	5	Response Total	Response Average
Cafeteria Space	17.76% (19)	10.28% (11)	29.91% (32)	17.76% (19)	24.3% (26)	107	3.21
Library Media Center	11.43% (12)	11.43% (12)	22.86% (24)	21.9% (23)	32.38% (34)	105	3.52
Office Areas	3.85% (4)	4.81% (5)	30.77% (32)	25% (26)	35.58% (37)	104	3.84
Art Rooms	13.33% (14)	10.48% (11)	34.29% (36)	20.95% (22)	20.95% (22)	105	3.26
Music Rooms	10.48% (11)	8.57% (9)	33.33% (35)	25.71% (27)	21.9% (23)	105	3.4
Performance spaces	14.02% (15)	10.28% (11)	28.97% (31)	24.3% (26)	22.43% (24)	107	3.31
Gymnasium	9.8% (10)	6.86% (7)	34.31% (35)	13.73% (14)	35.29% (36)	102	3.58
Student Support Services	19.81% (21)	18.87% (20)	31.13% (33)	12.26% (13)	17.92% (19)	106	2.9
Storage Space	12.38% (13)	12.38% (13)	30.48% (32)	19.05% (20)	25.71% (27)	105	3.33
Overall Technology	23.15% (25)	18.52% (20)	22.22% (24)	16.67% (18)	19.44% (21)	108	2.91
						Total Respondents	111

8. Grade for the condition of the Elementary School building.

	Response Total	Response Percent
A	20	18%
B	53	48%
C	31	28%
D	7	6%
F	0	0%
Total Respondents		111

9. Grade for the condition of the Jr.-Sr. High School building.

	Response Total	Response Percent
A	9	8%
B	44	40%
C	41	37%
D	15	14%
F	2	2%
Total Respondents		111

10. Comments

			Response Total	Response Percent
view	Comments		44	100%
			Total Respondents (skipped this question)	44 67