date last updated: 10/28/2020

Lab ELAP id#: 10709					Method of analysis: ICP/MS - EPA 200.8 REV 5.4			
Lab ID#	School sample id	collection date	Sample location	Outlet description	Initial/post remediation	Lead result ug/L (ppb)	lab report receipt date	Action Taken
201002059-001	16	10/2/2020	Elementary Kitchen	Prep Sink (left)	Initial	Not Detected (<1)	10/14/2020	n/a
201002059-002	17	10/2/2020	Elementary Kitchen	Prep Sink (right)	Initial	Not Detected (<1)	10/14/2020	n/a
201002059-003	18	10/2/2020	Elementary Kitchen Prep Island	Sink	Initial	Not Detected (<1)	10/14/2020	n/a
201002059-004	19	10/2/2020	Elementary Kitchen (Back Wall)	Sink	Initial	9.8	10/14/2020	n/a
201002059-005	20	10/2/2020	Elementary Kitchen	Kettle Fill	Initial	1.8	10/14/2020	n/a
201002059-006	21	10/2/2020	Elementary Boys Gym	Bottle Fill	Initial	Not Detected (<1)	10/14/2020	n/a
201002059-007	22	10/2/2020	Elementary Main Hall	Bottle Fill	Initial	Not Detected (<1)	10/14/2020	n/a
201002059-008	23	10/2/2020	Elementary Nurses Office	Sink	Initial	Not Detected (<1)	10/14/2020	n/a
201002059-009	24	10/2/2020	Elementary Faculty Break Room	Sink	Initial	Not Detected (<1)	10/14/2020	n/a
201002059-010	25	10/2/2020	Elementary Kitchen	Ice Maker	Initial	Not Detected (<1)	10/14/2020	n/a